



## Examination Reports of High Pressure Hose Pipe

1. Name of Occupier of the Factory : **M/s Kamlesh Kumar Singh.**
2. Address of the factory : C/o Site: P-25 Project, IOCL Panipat Refinery  
Haryana
3. Distinguishing number of mark, if any and Description  
Sufficient to identify lifting machine, chain, rope or the  
Lifting tackle : **High Pressure Hose Pipe**  
Length:- 5.0 mtr , Bore:- ¾ Inch, SWP:- 180 Bar  
**Sr. No/id mark.: 001**
4. Date when the lifting machine/ tackle was first taken to use  
in the factory. : As per site records.
5. Date and number of the certificate relating to any test and  
examination made under rule (1) and (7) together with the  
name and address of the person who issued the certificate. : Manufacturer tested
6. Date of each periodical thorough examination Made under  
sub clause (II) of clause (a) of subsection (1) of section 29 of  
the Act and sub rule (5) and by whom it was carried out : As per site records.
7. Date of annealing of other heat treatment of the chain and other  
lifting tackle made under sub-rule(5) and by whom it was carried  
out. : N.A.
8. Particulars of any defects affecting the Safe Working Load  
found at any such thorough examination or after annealing  
and the steps taken to remedy such defects. : Physically inspected and found satisfactory.

**Inspected on: 20/08/2024**

It is certified that I have thoroughly examined the above-mentioned High-Pressure Hose Pipe and above is a correct report of the result.

**Next inspection due date: 19/08/2025**



**Pankaj Kumar**

**Competent person**

**BE (Mech), PDIS, PDPC, MBA**



## Examination Reports of High Pressure Hose Pipe

1. Name of Occupier of the Factory : **M/s Kamlesh Kumar Singh.**
2. Address of the factory : C/o Site: P-25 Project, IOCL Panipat Refinery  
Haryana
3. Distinguishing number of mark, if any and Description  
Sufficient to identify lifting machine, chain, rope or the  
Lifting tackle : **High Pressure Hose Pipe**  
Length:- 1.5 mtr , Bore:- 3/4 Inch, SWP:- 180 Bar  
**Sr. No/id mark.: 002**
4. Date when the lifting machine/ tackle was first taken to use  
in the factory. : As per site records.
5. Date and number of the certificate relating to any test and  
examination made under rule (1) and (7) together with the  
name and address of the person who issued the certificate. : Manufacturer tested
6. Date of each periodical thorough examination Made under  
sub clause (II) of clause (a) of subsection (1) of section 29 of  
the Act and sub rule (5) and by whom it was carried out : As per site records.
7. Date of annealing of other heat treatment of the chain and other  
lifting tackle made under sub-rule(5) and by whom it was carried  
out. : N.A.
8. Particulars of any defects affecting the Safe Working Load  
found at any such thorough examination or after annealing  
and the steps taken to remedy such defects. : Physically inspected and found satisfactory.

**Inspected on: 20/08/2024**

It is certified that I have thoroughly examined the above-mentioned High-Pressure Hose Pipe and above is a correct report of the result.

**Next inspection due date: 19/08/2025**



**Pankaj Kumar**

**Competent person**

**BE (Mech), PDIS, PDPC, MBA**