

FORM NO.38

1.	Name of the Occupier (or Owner) of premises	:	
2.	Address of the factory	:	AmaraRaja Energy & Mobility Limited-ARGC-CD 2 Amar Raja Growth Corridor [ARGC], Nunegundlapalli Village,, Bangarupalyam Mandal, Chittoor District, Andhra Pradesh – 517422.
3.	a) Type of Hoist or Lift or Lifting Machinery/Tackle and Identification Number or Description	:	BATTERY OPERATED PALLET STACKER CAPACITY 1600 KGS LOCATION : DISPATCH ID NO CIX372F00284
	b) Date of Construction or re-construction (if ascertainable)	:	
	c) Date of last test & by whom	:	
4.	Design and construction (Are all Parts of the hoist or lift of good mechanical construction, sound material and adequate strength as far as ascertainable)	:	The Battery Operated Pallet Stacker is of standard design and construction
5.	Distinguished number of mark (if any) and description sufficient to identify the lifting machines, chain, ropes	:	MAKE ; LINDE , Model L-16 Lift Height : 6.3metres,
6.	Maintenance Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found.	:	Yes, They are in good working condition. No defects found
	a) Enclosure of Hoist way or Lift way	:	Not Applicable
	b) Landing gates and cage gate(s)	:	Not Applicable
	c) Interlocks on the landing gate(s) and cage gate(s)	:	Not Applicable
	d) Other gauges, fastenings	:	Fasteners are fixed as per the standards
	e) Cage & platforms and fittings, guides, buffers, interiors of the Hoist way or Lift way	:	Not Applicable
	f) Over-running devices	:	Yes
	g) Suspension ropes or chain & their attachments	:	Yes, Well maintained
	h) Safety gear i.e. arrangements for preventing fall of platform or Cage brakes	:	Yes
	i) Brakes	:	Checked and working satisfactorily.
	j) Worm or spur gearing	:	Yes
	k) Other electrical equipment	:	Yes, working satisfactorily
	l) Other parts	:	Yes
7.	What part (if any) were inaccessible	:	All parts are accessible
8.	a) Repairs, renewals or alterations (if any) required and the period within which they should be executed	:	No repairs/ Alterations required
	b) Particulars of the parts of Hoists or Lifts or Lifting Machinery/tackle rejected after the examination	:	NIL
9.	Maximum safe working load subject to repairs, renewals or alterations (if any) specified in column No.6(a)	:	The Battery Operated Pallet Stacker is fit for working with a load of 1600 kgs
10.	Others	:	Thorough visual inspection carried out . There are no damages while working with the load. Hydraulic system, Tyres, Brakes, Horns, indicators, Safety systems are working satisfactorily. The Battery Operated Pallet Truck is in satisfactory condition,

I certify that on **03/12/2024**, I thoroughly examined the hoist or lift and that the above is a correct report of the result.



Certificate No. :
Date of Issue : 03/12/2024
Next Testing Due on : 09/08/2025

D.N.MARGABANDU
Chartered Engineer
Competent Person
FOR HimTex Global

